

MODEL 950.0 /1 /2 /3, 952.0 /1 /2 /3, 953.1 /3, 954.0 /1 /2

Fault code	Fault code description
1010	Control unit: internal fault
1101	Terminal 30: overvoltage
1102	Terminal 30: undervoltage
2021	Feed line to the FB interface has a short circuit to ground (plausibility during transmission).
2221	Feed line to the GGVS output has a short circuit to ground.
2222	Feed line to the GGVS output has a short circuit to positive.
3021	Feed line to the 'M+' actuator of the driver door has a short circuit to ground.
3022	Feed line to the 'M+' actuator of the driver door has a short circuit to positive.
3121	Feed line to the 'M-' actuator (interior light) of the driver or front passenger door has a short circuit to ground.
3122	Feed line to the 'M-' actuator (interior light) of the driver or front passenger door has a short circuit to positive.
3221	Feed line to the 'M+' actuator of the front passenger door has a short circuit to ground.
3222	Feed line to the 'M+' actuator of the front passenger door has a short circuit to positive.
3321	Feed line to the 'lock' interior button has a short circuit to ground.
3421	Feed line to the 'unlock' interior button has a short circuit to ground.